

## REFERENCE TABLES

### CONVERT INCHES TO MILLIMETERS

To convert inches to millimeters multiply by 25.4.

FRACTION	INCHES	M/M	FRACTION	INCHES	M/M	FRACTION	INCHES	M/M
1/64	.01563	.397						
<b>1/32</b>	<b>.03125</b>	<b>.794</b>	23/64	.35938	9.128	45/64	.70313	17.859
3/64	.04688	1.191	<b>3/8</b>	<b>.375</b>	<b>9.525</b>	<b>23/32</b>	<b>.71875</b>	<b>18.2564</b>
			25/64	.39063	9.922	7/64	.73438	18.653
<b>1/16</b>	<b>.0625</b>	<b>1.587</b>	<b>13/32</b>	<b>.40625</b>	<b>10.319</b>	<b>3/4</b>	<b>.750</b>	<b>19.05</b>
5/64	.07813	1.984	27/64	.42188	10.716	49/64	.76563	19.447
<b>3/32</b>	<b>.09375</b>	<b>2.381</b>	<b>7/16</b>	<b>.4375</b>	<b>11.113</b>	<b>25/32</b>	<b>.78125</b>	<b>19.844</b>
7/64	.10938	2.778	29/64	.45313	11.509	51/64	.79688	20.241
<b>1/8</b>	<b>.125</b>	<b>3.175</b>	<b>15/32</b>	<b>.46875</b>	<b>11.906</b>	<b>13/16</b>	<b>.8125</b>	<b>20.637</b>
9/64	.14063	3.572	31/64	.48438	12.303	53/64	.82813	21.034
<b>5/32</b>	<b>.15625</b>	<b>3.969</b>	<b>1/2</b>	<b>.500</b>	<b>12.700</b>	<b>27/32</b>	<b>.84375</b>	<b>21.431</b>
11/64	.17188	4.366	33/64	.51563	13.097	55/64	.85938	21.828
<b>3/16</b>	<b>.1875</b>	<b>4.762</b>	<b>17/32</b>	<b>.53125</b>	<b>13.494</b>	<b>7/8</b>	<b>.875</b>	<b>22.225</b>
13/64	.20313	5.159	35/64	.54688	13.891	57/64	.89063	22.622
<b>7/32</b>	<b>.21875</b>	<b>5.556</b>	<b>9/16</b>	<b>.5625</b>	<b>14.287</b>	<b>29/32</b>	<b>.90625</b>	<b>23.019</b>
15/64	.23438	5.953	37/64	.57813	14.684	59/64	.92188	23.416
<b>1/4</b>	<b>.250</b>	<b>6.35</b>	<b>19/32</b>	<b>.59375</b>	<b>15.081</b>	<b>15/16</b>	<b>.9375</b>	<b>23.812</b>
17/64	.26563	6.747	39/64	.60938	15.478	61/64	.95313	24.209
<b>9/32</b>	<b>.28125</b>	<b>7.144</b>	<b>5/8</b>	<b>.625</b>	<b>15.875</b>	<b>31/32</b>	<b>.96875</b>	<b>24.606</b>
19/64	.29688	7.541	41/64	.64063	16.272	63/64	.98438	25.003
<b>5/16</b>	<b>.3125</b>	<b>7.937</b>	<b>21/32</b>	<b>.65625</b>	<b>16.669</b>	<b>1</b>	<b>1.00</b>	<b>25.4</b>
21/64	.32813	8.334	43/64	.67188	17.066			

