

REFERENCE TABLES

CONVERT INCHES TO MILLIMETERS

To convert inches to millimeters multiply by 25.4.

FRACTION	INCHES	M/M	FRACTION	INCHES	M/M	FRACTION	INCHES	M/M
1/64	.01563	.397						
1/32	.03125	.794	23/64	.35938	9.128	45/64	.70313	17.859
3/64	.04688	1.191	3/8	.375	9.525	23/32	.71875	18.2564
			25/64	.39063	9.922	7/64	.73438	18.653
1/16	.0625	1.587	13/32	.40625	10.319	3/4	.750	19.05
5/64	.07813	1.984	27/64	.42188	10.716	49/64	.76563	19.447
3/32	.09375	2.381	7/16	.4375	11.113	25/32	.78125	19.844
7/64	.10938	2.778	29/64	.45313	11.509	51/64	.79688	20.241
1/8	.125	3.175	15/32	.46875	11.906	13/16	.8125	20.637
9/64	.14063	3.572	31/64	.48438	12.303	53/64	.82813	21.034
5/32	.15625	3.969	1/2	.500	12.700	27/32	.84375	21.431
11/64	.17188	4.366	33/64	.51563	13.097	55/64	.85938	21.828
3/16	.1875	4.762	17/32	.53125	13.494	7/8	.875	22.225
13/64	.20313	5.159	35/64	.54688	13.891	57/64	.89063	22.622
7/32	.21875	5.556	9/16	.5625	14.287	29/32	.90625	23.019
15/64	.23438	5.953	37/64	.57813	14.684	59/64	.92188	23.416
1/4	.250	6.35	19/32	.59375	15.081	15/16	.9375	23.812
17/64	.26563	6.747	39/64	.60938	15.478	61/64	.95313	24.209
9/32	.28125	7.144	5/8	.625	15.875	31/32	.96875	24.606
19/64	.29688	7.541	41/64	.64063	16.272	63/64	.98438	25.003
5/16	.3125	7.937	21/32	.65625	16.669	1	1.00	25.4
21/64	.32813	8.334	43/64	.67188	17.066			

