

REFERENCE TABLES

CONVERT MILLIMETERS TO INCHES

To convert millimeters to inches multiply by .0394.

MM	Inches	MM	Inches	MM	Inches	MM	Inches
1	.0394	26	1.0244	51	2.0094	76	2.9944
2	.0788	27	1.0638	52	2.0488	77	3.0338
3	.1182	28	1.1032	53	2.0882	78	3.0732
4	.1576	29	1.1426	54	2.1276	79	3.1126
5	.1970	30	1.1820	55	2.1670	80	3.1520
6	.2364	31	1.2214	56	2.2064	81	3.1914
7	.2758	32	1.2608	57	2.2458	82	3.2308
8	.3152	33	1.3002	58	2.2852	83	3.2702
9	.3546	34	1.3396	59	2.3246	84	3.3096
10	.3940	35	1.3790	60	2.3640	85	3.3490
11	.4334	36	1.4184	61	2.4034	86	3.3884
12	.4728	37	1.4578	62	2.4428	87	3.4278
13	.5122	38	1.4972	63	2.4428	88	3.4672
14	.5516	39	1.5366	64	2.5216	89	3.5066
15	.5910	40	1.5760	65	2.5610	90	3.5460
16	.6304	41	1.6154	66	2.6004	91	3.5854
17	.6698	42	1.6548	67	2.6398	92	3.6248
18	.7092	43	1.6942	68	2.6792	93	3.6642
19	.7486	44	1.7336	69	2.7186	94	3.7036
20	.7880	45	1.7730	70	2.7580	95	3.7430
21	.8274	46	1.8124	71	2.7974	96	3.7824
22	.8668	47	1.8518	72	2.8368	97	3.8218
23	.9062	48	1.8912	73	2.8762	98	3.8612
24	.9456	49	1.9306	74	2.9156	99	3.9006
25	.9850	50	1.9700	75	2.9550		